

Classification:

BR08-007

Reference:

ITB09-007

COPYRIGHT© NISSAN NORTH AMERICA, INC.

Date:

January 30, 2009

ABS DTC C1142 STORED

APPLIED VEHICLES: 2007 – 2008 G35 Sedan (V36)
2007 G35 Coupe (CV35)
2009 G37 Sedan (V36)
2008 – 2009 G37 Coupe (CV36)
2006 – 2009 M35/M45 (Y50)

IF YOU CONFIRM

DTC code C1142 is stored in the ABS system,

NOTE: If code C1142 is stored, the ABS, SLIP, and VDC OFF lights will likely be ON.

ACTIONS

Follow the flow chart in the Service Procedure for diagnostic and repair steps.

NOTE: Make sure the brake pedal and stop lamp switch adjustments are correct, and the stop lamp switch and circuit are operating correctly before replacing the ABS Actuator and Electronic Control Unit.

IMPORTANT: The purpose of “ACTIONS” (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire Service Procedure as it contains information that is essential to successfully completing this repair.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, **DO NOT** assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QTY
ABS Actuator and Electronic Control Unit	Refer to an electronic parts catalog (FAST or equivalent). Use the VIN to determine the correct part for your vehicle.	1; if needed
Stop Lamp Switch	Refer to an electronic parts catalog (FAST or equivalent). Use the VIN to determine the correct part for your vehicle.	1; if needed

CLAIMS INFORMATION

Submit a Primary Operation (PO) type line claim using the following claims coding:

DESCRIPTION	OP CODE	SYM	DIA	FRT
Check and Adj. Brake Pedal and Stop Lamp Switch as Needed, and Perform C-III Diagnostics	PX41AA	ZE	41	0.3

And, if needed, on a separate line

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace ABS Actuator Assy	(1)	PN30AA	ZE	23	(2)

(1) Refer to the electronic parts catalog (FAST or equivalent) and use the appropriate ABS Actuator and Electronic Control Unit P/N as the PFP.

(2) Refer to the current Infiniti Warranty Flat Rate Manual and use the indicated FRT.

OR

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Replace Stop Lamp Switch	(3)	PF26AA	ZE	23	(4)

(3) Refer to the electronic parts catalog (FAST or equivalent) and use the appropriate Stop Lamp Switch P/N as the PFP.

(4) Refer to the current Infiniti Warranty Flat Rate Manual and use the indicated FRT.

OR

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Repair Stop Lamp Circuit	(5)	Reference the current Infiniti Warranty Flat Rate Manual – Section RA - and use the appropriate warranty claims coding.			

(5) Refer to the electronic parts catalog (FAST or equivalent) and use the appropriate Wiring Harness P/N as the PFP.

SERVICE PROCEDURE



